


6 Speed Automatic Transmission Harness (6.0L)



- (1) Heated Oxygen Sensor (HO2S) Bank 1 Sensor 2 Connector -- B57
- (2) Heated Oxygen Sensor (HO2S) Bank 2 Sensor 1 Connector -- B166
- (3) Heated Oxygen Sensor (HO2S) Bank 2 Sensor 2 Connector -- B57
- (4) Automatic Transmission Connector -- X121